




2011-10-19

TVS Test one wire




yo need for yo
>>>




clating frequency
ideal frequency 20.9 kHz
same structure

NOT WORC !!!! bed
TVC Freqeance .
and + voltages
amplitude . NOT
Good !!!

very good >> wen
about 0.025 A



very good >>



NOT WORC !!!! bed
contur resonacee
. NOT Good !!!

